



## Transfer SI Data to Backup Media (flash drive, zip drive, etc.)

1. On the **Dredge Display** screen click "**COPY DATA To ZIP/USB**" button



2. In the **Dredge Data Transfer** screen, if the correct date of the last backup appears beside the "**Backup – date**" button continue on to step 4 otherwise, select "**This day and hour...**"



3. Enter the date of the last backup, if unknown enter date the dredging began.
4. Click the "**Transfer**" button
5. Wait for the transfer to complete and then **exit**.
6. Remove the zip disk or jump drive, you're done.

Feel free to give me call for further assistance. My contact info is listed below.

Rhonda Lenoir, SI Training and Technical Support  
SI National Support Center ([chl-sics@erdc.usace.army.mil](mailto:chl-sics@erdc.usace.army.mil))  
COE, Mobile District  
(251)690-3011 (v)  
(601)618-0755 (c)  
[Rhonda.M.Lenoir@usace.army.mil](mailto:Rhonda.M.Lenoir@usace.army.mil)